

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	10	Dodda Bommasandra
Street ID	Street Name	Significant Landmark
W0252, W0313, W0309, W0315	NA	Gangamma Gudi area
Segment No.	Total Length (m)	
10/C-W0252/S080802	298.44	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	43.42	77.548916	13.056945	77.548929	13.057338	W0252	DEAD END
2	45.10	77.548649	13.056939	77.548655	13.057347	W0252	I0246
3	209.92	77.548350	13.057512	77.548240	13.055618	I0246	M0005

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drains at Gangamma Gudi area in ward no 10 Doddabommasandra Vidyanayapura Sub-Division Yelahanka zone	2500000	2016
Year	Type of Work	Other Work Type
2016 - 2017	Asphalting	
Tender	Work Details	Job No. / Work Code
Not a Tender	Improvements to Roads and Drains at Gangamma Gudi area in ward no 10 Doddabommasandra Vidyanayapura Sub-Division Yelahanka zone	010-17-000001
Work Order No.	Work Order Date	Period of Extention
BBMP/EE/BTP/WO/108/2016-17	19/08/2016	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
19/08/2016	18/08/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00
Phone No.	E-Mail ID	

Zone: YELAHANKA

Ward No: 10

Ward Name: Dodda Bommasandra

Street ID: W0252,
W0313,
W0309,
W0315

Field Inspection Details

Number of Trees

4

Any Other Information

Name

MADHAVA RAO

Date of Inspection

07/12/2016

Remarks

COMPLETED


Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA

Ward No: 10

Ward Name: Dodda Bommasandra

Street ID: W0252,
W0313,
W0309,
W0315

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks				
Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAI AH	07/12/2016	06/01/2017	COMPLETED
SE	VASU K M	07/12/2016	06/01/2017	COMPLETED
EE	YARAPPA REDDY	07/12/2016	06/01/2017	COMPLETED
AEE	SHIVAKUMAR	07/12/2016	06/01/2017	COMPLETED
AE	MADHAV RAO	07/12/2016	06/01/2017	COMPLETED
AE	MADHAV RAO	07/12/2016	06/01/2017	COMPLETED